

Version: **RCX 1.0-1-02**

Type: Bugfix

Reference: #34761

Description:

NO/NC settings revert to default after loss of power

If the inputs UI1 and/or UI2 is used as digital input and NC is chosen during configuration of the unit, the unit will revert to NO (default) after a loss of power. This issue is now fixed.

Version: **RCX 1.0-1-01**

Type: Bugfix

Reference: #N/A

Description:

Improved sensor readout

In rare circumstances sensor readout could temporarily fail. This is now fixed. Non-critical update.

AB Regin

Tel: +46 31 720 02 00
E-mail: info@regin.se
www.regincontrols.com

Address:
Bangårdsvägen 35
428 36 Kållerød